



7%±2%

 $>500 \, kg/m^3$

OAK PALLIDO

The barely-there sepia stain on this single-strip oak floor from the Boardwalk Collection allows natural tones to show through, while highlighting a characterful formation of knots and cracks. Each board is carefully brushed to bring out the grain and four-sided beveling ensures a classic full plank look.

PRODUCT DETAILS		PRODUCT DETAILS	
Product type / Construction	Wood Flooring / 3-layer parquet	Hardness (Brinell) value	
Article Number / EAN Code	151NDMEK10KW240 / 7393969046084	range	
Design / Wood Species	1-strip / Oak	LRV / LRV Std1	
Surface Treatment /	Oil / Stained	Warranty	
Natural/Stained		— TECHNICAL PROPERT	
Refining Treatment	Microbevelled 4-sided, Brushed	Moisture content	
Width x Length x Thickness	187 x 2420 x 15 mm	Minimun Mean Density kg/m³	
Weight per package / per	22 kg / 8.15 kg		
m2		— Reaction To Fire	
Area per package / per	2.7 m ² / 122.4 m ²	Formaldehyde Emission	
pallet		— Content PCP	
Grading	Dynamic	Breaking Strength N/mn	
Joint	Woodloc® 5S	Thermal Resistance R-Va	
Installation method	Floating, Glue-down	-	
Floor heating	Yes	Biological Durability	
Wear leayer material /	Hardwood / 3.5 mm	CARB2	
thickness		Slip resistance	
Resandable	2-3 times	ENSOION CONSTITUTE ON CONTRACT TO	
Core material	Pine/Spruce/Alder	WE MID SO A+ SCO	
Backside material	Spruce		

PROD	UCT	DETA	ILS

Hardness (Brinell) value /	3,7 / 2.2 - 5.9
range	
LRV / LRV Std1	29 / 7.4
Warranty	30 years

OPERTIES

Willillian Wear Density		2000 Kg/III
kg/m³		
Reaction To Fire	EN13501-1	Dfl-s1
Formaldehyde Emission	EN717-1	E1
Content PCP	CEN/TR14823	≤ 5 x 10-6n
Breaking Strength N/mm²	EN1533	NPD
Thermal Resistance R-Value		.11 (m2K/W)
Biological Durability	EN350-2	Class 1
CARB2		Compliant
Slip resistance	CEN/TS15676	NPD
•	·	

EN13183







DETAILED DESCRIPTION

All naturally occuring wood colour variations allowed, from light to dark brown. Sapwood may occur. The product includes large sound and black knots. Knots, fillings and cracks will be present in all sizes and numbers.

Oil: This floor should be oiled immediately after installation.

Colour change: Stained product - noticeable color change over time.

Packages may contain start and stop boards.

Other products in this collection









OAK LUCE OAK OMBRA

OAK PALLIDO OAK TRAMONTO